

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
7	Road No A258 Grid 636242E Section 120 Ref 151899N	SLIGHT	22/06/2015	2	18:20	L	Wet/Damp	Fine			GV P/C
A258, London Road, Deal, Kent									Dover		
V2 was Travelling Along London Road Towards the Roundabout which Leads to Manor Road. as V2 Approached the Roundabout, they Came to a Stop Due to Slowing Traffic and Congestion Whilst V2 was Stationary, they Heard a Loud Bang/Thud to the Back of their Van. D2 Got out of their Van to Look and Saw the Cyclist (V1) Lying on the Side of the Road Unconscious Witness 1 States That (V1) Cyclist was Not Paying Attention as they were Txting on their Phone, Causing them to Collide with the Back of V2							Veh1, pedal cycle, SE -> NW Veh2, goods < 3.5t, SE -> NW			Casualties 1 Vehicles 2	
8	Road No E3314 Grid 636950E Section 001 Ref 152092N	SLIGHT	28/07/2015	3	15:52	L	Dry	Unknown			
Park Avenue, Deal, Kent (Mapped to 636950, 152100)									Dover		
V2 was Parked Along Park Avenue, Halfway down Road. Cas was in the Rear - Leaning with the Rear Passenger Door Open to Get Child's Seatbelt On. V1 Has Driven Past and Hit V2's Door Banging the Door into Cas' Legs. V1 Did Not Stop.							Veh1, car, E -> W Veh2, car, P -> P			Casualties 1 Vehicles 2	
9	Road No A258 Grid 636815E Section 111 Ref 152084N	SLIGHT	08/09/2015	3	10:00	L	Dry	Fine		S.VEH	PSV
London Road Jw Park Avenue, Deal									Dover		
V1 (Bus) Had to Brake Sharply to Avoid a Collision with the Vehicle in Front, Causing the Passengers to Be Thrown Forward.							Veh1, bus or coach, W -> NE			Casualties 2 Vehicles 1	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight
STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
10	Road No E3313 Grid 636892E Section 001 Ref 151766N	SLIGHT	17/10/2015	7	10:30	L	Dry	Fine	Stand	S.VEH	GV
	Mill Road, Outside Number 161, Deal, Kent									Dover	PED
an Altercation Took Place Between C1 and V1. V1 Went to Drive Away, C1 Hit Rear of Veh as Thought it was Going to Drive over Delivered Goods but V1 Did Not Stop and Hit C1 Arm.							Veh1, goods < 3.5t, NE -> SW			Casualties 1 Vehicles 1	
11	Road No A258 Grid 635591E Section Ref 152467N	SLIGHT	17/02/2016	4	16:40	L	Wet/Damp	Fine			HGV
	A258 LONDON ROAD 20 METRES S/E OF J/W SHOLDEN NEW ROAD, DEAL									Dover	
ALL 3 VEHICLES WERE TRAVELLING OUT OF DEAL TOWARDS SANDWICH ON THE A258. VEHICLE 3 WAS HELD UP APPROACHING JUNCTION WITH SHOLDEN NEW ROAD. (V1) UNABLE TO STOP COLLIDED WITH THE REAR OF (V2) PUSHING IT INTO THE REAR OF (V3).							Veh1, car, SE -> NW Veh2, car, W -> NW Veh3, goods 3.5 - 7.5t, SE -> NW			Casualties 1 Vehicles 3	
12	Road No A258 Grid 636875E Section Ref 152154N	SLIGHT	02/05/2016	2	23:20	DRK STL	Dry	Fine			
	A258 LONDON ROAD J/W BOWLING GREEN LANE, DEAL									Dover	
V2 went to pull put of Bowling Green Lane onto London Road, stopped when saw veh 1 travelling fast northbound.V1 collided with front of v2 and v1 failed to stop, made off towards Town Centre- no driver known							Veh1, car, SW -> NE Veh2, car, NW -> S			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
13	Road No U Grid 637053E Section 001 Ref 151987N	SERIOUS	22/07/2016	6	17:30	L	Dry	Fine	E	S.VEH	
MILL ROAD, OUTSIDE 162, DEAL									Dover	PED	
C1 RAN OUT FROM BETWEEN PARKED VEHICLES INTO PATH OF V1 AND WAS STRUCK BY FRONT OF V1 CAUSING INJURY							Veh1, car, S -> N			Casualties 1 Vehicles 1	
14	Road No A258 Grid 636265E Section 119 Ref 151937N	SLIGHT	29/07/2016	6	17:15	L	Dry	Fine	NW	S.VEH	
A258 LONDON ROAD, ZEBRA CROSSING O/S LONDIS, DEAL									Dover	PED	
C1 was on zebra crossing wheeling their push bike beside them. Crossing from o/s Londis store to the other side. A veh stopped on that side to allow C1 to cross so they stepped onto the crossing. No traffic on the other side. They were about three quarters of the way across when they became aware of another car (V1) approaching from the roundabout junction. C1 carried on but the V1 failed to stop, clipped the rear bike wheel causing it to fall onto C1, making them fall onto the crossing. D1 was aware of what had happened as they faltered for a moment and then deliberately drove around C1 and bike as they lay on the crossing. No other persons around so inft picked themselves up, walked home. Inft has a gravel burn about two and a half inches long on their right forearm and bruising and swelling to their right wrist. Also has slight bruising to their right leg. There is minor damage to push bike, scratches to wheel supports.							Veh1, car, SW -> NE			Casualties 1 Vehicles 1	

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight
 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
15	Road No A258 Grid 635578E Section 129 Ref 152488N	SLIGHT	17/08/2016	4	19:38	L	Dry	Fine			
A258, LONDON ROAD J/W SHOLDEN NEW ROAD, SHOLDEN									Dover		
V1 AND V2 TRAVELLING ALONG LONDON ROAD, SHOLDEN, V2 FRONT VEHICLE BEING FOLLOWED BY V1, V2 SUDDENLY BRAKED AND TURNED LEFT ONTO SHOLDEN NEW ROAD, V1 COLLIDED WITH REAR NEARSIDE OF V2, IT IS ALLEGED V2 DID NOT GIVE ANY INDICATION.							Veh1, car, NW -> SE Veh2, car, NW -> SE			Casualties 1 Vehicles 2	
16	Road No B2056 Grid 636480E Section 004 Ref 151715N	SLIGHT	22/08/2016	2	07:30	L	Dry	Fine		S.VEH	
B2056, MONOR ROAD, O/S 59									Dover		P/C
V1 RIDER CAME OFF PEDAL CYCLE, NO SUGGESTED INVOLVEMENT FROM OTHER VEHICLES.							Veh1, pedal cycle, S -> N			Casualties 1 Vehicles 1	
17	Road No A258 Grid 635309E Section 131 Ref 152757N	SLIGHT	11/09/2016	1	00:01	L	Dry	Fine			
A258, LONDON ROAD, SHOLDEN, DEAL (MAPPED TO 635309,152757)									Dover		
V1 (INFT) WAS DRIVING BY THE ENTRANCE TO THE NEW SHOLDEN FIELDS ESTATE WHEN V2 HIT THEM FROM BEHIND. THEN V2 DROVE OFF AND THE INFORMANT FOLLOWED THEM. THEY THEN EXCHANGED THEIR DETAILS AS PER SECTION 170 RTA.							Veh1, car, NW -> SE Veh2, car, NW -> SE			Casualties 2 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
18	Road No U Section	Grid 636882E Ref 151766N	SERIOUS	03/10/2016	2	00:01	L	Dry	Fine		
	MILL ROAD, O/S 244, DEAL									Dover	
V1 WAS TRAVELLING ALONG MILL ROAD WHEN THE DRIVER MIS-JUDGED THE WIDTH OF THE ROAD AND HIT INTO THE FRONT OF V2 WHICH WAS PARKED, V2 THEN HIT V3, V3 WAS ALSO PARKED.							Veh1, car, Uk -> Uk Veh2, car, Uk -> Uk Veh3, car, Uk -> Uk			Casualties 4 Vehicles 3	
19	Road No U Section	Grid 637178E Ref 152150N	SERIOUS	04/10/2016	3	01:50	DRK STL	Dry	Fine		
	MILL ROAD O/S 112 J/W PARK AVENUE, DEAL									Dover	
V1 was seen by unmarked police vehicle to struggle with manoeuvre of turning around. V1 was followed and seen to mount kerb. Initially the vehicle stopped for police but then made off at excess speed. V1 failed to negotiate the road ahead and crashed into residential front garden walls and roadside furniture, which caused V1 to end up on it's nearside. Occupants exited via window and detained and arrested by police							Veh1, car, SW -> NE Veh2, car, SW -> NE			Casualties 2 Vehicles 2	
20	Road No A258 Section 113	Grid 636725E Ref 152039N	SLIGHT	12/12/2016	2	20:00	DRK STL	Dry	Fine		S.VEH
	A258, LONDON ROAD, DEAL (MAPPED TO 636717,152022)									Dover	
C1 STATES THEY WAS DRIVING ALONG WHEN THEY HEARD A BANG WHICH MADE C1 THEN NOT HAVE CONTROL OF V1 AND HIT A WALL. NO OTHER PERSON OR CAR INVOLVED THE PERSONS WALL WHO C1 HIT HAVE EXCHANGED DETAILS.							Veh1, car, Uk -> Uk			Casualties 1 Vehicles 1	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
21	Road No A258 Grid 635467E Section 130 Ref 152622N	SLIGHT	24/01/2017	3	10:33	L	Wet/Damp	Unknown			
A258 SANDWICH ROAD, DEAL (MAPPED TO 635467,152622)									Dover		
V2 was travelling on Sandwich Road towards Deal. V2 had stopped behind a bus and V1 collided with the back of V2. D2 got out of V2 to speak with D1. D1 suggested that both cars pull over into a layby to exchange details. D2 agreed, however D1 drove off without stopping.							Veh1, car, SE -> NW Veh2, car, SE -> NW			Casualties 1 Vehicles 2	
22	Road No U Grid 635548E Section 001 Ref 151919N	SERIOUS	04/02/2017	7	11:03	L	Wet/Damp	Rain			
MONGEHAM ROAD, 2 METRES WEST OF J/W ST MARTINS ROAD, SHOLDEN									Dover		
V1 WAS DRIVING ON MONGEHAM ROAD TOWARDS LONDON ROAD DEAL, V2 WAS DRIVING ON MONGEHAM ROAD AWAY FROM LONDON ROAD. V2 SAW V1 APPROACHING SO CAME TO A STOP NEAR TO ST MARTINS RD NEXT TO A PARKED VEHICLE. V1 CONTINUED TO DRIVE ALONG MONGEHAM ROAD AND COLLIDED WITH THE FRONT OF V2 WHICH WAS STATIONARY.							Veh1, car, SW -> NE Veh2, car, NE -> SW			Casualties 3 Vehicles 2	
23	Road No U Grid 636897E Section 001 Ref 152084N	SLIGHT	14/03/2017	3	18:58	DRK STL	Dry	Fine			
PARK AVENUE, OUTSIDE NO.72, DEAL									Dover		
V1 and V2, travelling in opposite directions, collided passing legally parked vehicles on Park Avenue.							Veh1, car, E -> W Veh2, car, W -> E			Casualties 3 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
24	Road No A258 Grid 636299E Section 119 Ref 151961N	SLIGHT	30/06/2017	6	12:50	L	Dry	Fine			
A258 LONDON ROAD, APPROACH TO MANOR ROAD, DEAL (MAPPED TO 636296,151964)									Dover		
V2 was slowing for queuing traffic ahead when V1 struck the rear of V2 causing damage and injury to D2. V1 failed to stop and report, overtaking queuing vehicles and making off.							Veh1, car, NE -> SW Veh2, car, NE -> SW			Casualties	1
										Vehicles	2
25	Road No U Grid 636691E Section 008 Ref 151528N	SLIGHT	30/06/2017	6	18:30	L	Dry	Fine		R.TURN	P/C
MILL HILL J/W B2056 MILL RD, DEAL.									Dover		
C1 was riding their pedal cycle on Mill road in a NW direction around the bend where there is a junction with Mill Hill. V1 did not stop or see C1 as it joined Mill Hill at the give way junction heading in a NE direction towards Victoria Park. V1 collided with C1, knocking them to the floor and buckling the front wheel of the pedal cycle. C1 said that they were uninjured. Advice sought from off duty paramedic present and deemed it appropriate for PCSO to drive C1 home in patrol car, witness details, IP's details and R/O details recorded in PNB.							Veh1, car, SW -> NE Veh2, pedal cycle, NE -> NW			Casualties	1
										Vehicles	2
26	Road No U Grid 637159E Section 001 Ref 152131N	SLIGHT	14/09/2017	5	08:46	L	Dry	Fine		R.TURN	P/C
MILL ROAD AT J/W PARK AVENUE, DEAL (MAPPED TO DESCRIPTION. ORIGINAL CO-ORDS: 637435,152418)									Dover		
V1 travelling along Park Avenue towards Victoria Park, Deal. V1 decided to turn right cutting the corner onto Mill Road. As V1 cut the corner cyclist travelling towards junction of Mill Road and Park Avenue was hit by V1 causing the cyclist to be injured and requiring to be conveyed to hospital.							Veh1, car, W -> S Veh2, pedal cycle, S -> N			Casualties	1
										Vehicles	2

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved	
27	Road No U Section 111	Grid 636851E Ref 152084N	SLIGHT	20/09/2017	4	08:30	L	Dry	Fine	S	S.VEH	
	PARK AVENUE NEAR JN WITH A258 LONDON ROAD, DEAL (MAPPED TO CO-ORDS)									Dover	PED	
V1 TURNED RIGHT FROM LONDON ROAD TO PARK AVENUE. PEDESTRIAN STEPPED OUT IN FRONT OF V1 FROM THE FOOTPATH.							Veh1, car, NW -> SE			Casualties	1	
										Vehicles	1	
28	Road No U Section 001	Grid 635332E Ref 151744N	SLIGHT	26/04/2018	5	17:20	L	Dry	Fine			P/C
	MONGEHAM RD J/W CAR PARK, DEAL.									Dover		
V2 WAS TURNING LEFT INTO A CAR PARK ON MONGEHAM RD, WHEN A CYCLIST UNDER TOOK ON THE NEARSIDE AND COLLIDED WITH V2'S REAR SIDE. (POSTCODE FOR V1/C1 NOT KNOWN)							Veh1, pedal cycle, SW -> NE Veh2, car, NE -> SE			Casualties	1	
										Vehicles	2	
29	Road No A258 Section 001	Grid 636834E Ref 152106N	SLIGHT	27/05/2018	1	00:50	DRK STL	Dry	Fine	NW	S.VEH	
	A258, LONDON RD, O/S HOSPITAL, DEAL, (RE-MAPPED, OLD COORDS 636757,151987)									Dover	PED	
WALKING ALONG LONDON ROAD, DEAL, HEADING TOWARDS MILL HILL DIRECTION, IN BETWEEN TRAFFIC ISLANDS OUTSIDE HOSPITAL, HAD JUST CROSSED ROAD WHEN VEHICLE HEADING TOWARDS DEAL TOWN, HIT VICTIM, MAKING CONTACT WITH RIGHT SIDE. CLIPPED BY PART OF VEHICLE, VEHICLE FAILED TO STOP.							Veh1, car, SW -> NE			Casualties	1	
										Vehicles	1	

Key Involved

PED Pedestrian
 HGV Heavy Goods Vehicle
 GV Goods Vehicle
 M/C Motor Cycle
 P/C Pedal Cycle
 PSV Bus/Coach

Street Lighting

L Daylight
 STL Street Lights
 USL Street Lights Unlit
 NSL No Street Lights
 STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
 R.TURN Right Turn Manoeuvre
 O/TAKE Overtaking Manoeuvre
 S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
 ATS DEF Traffic Lights Defective
 SIGNS Road Signs Defective or Obscured
 RD WRKS Road Works
 Surface Road Surface Defective

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
30	Road No A258 Grid 636828E Section 111 Ref 152084N	SERIOUS	12/09/2018	4	17:40	L	Wet/Damp	Rain			P/C
A258 LONDON RD J/W PARK AVE, DEAL (MAPPED TO DESC. ORIGINAL COORDS - 636717,152022)									Dover		
V1 APPROACHED JUNCTION LONDON RD FROM PARK AVE, PULLING ALONG SIDE ANOTHER VEHICLE WHICH WAS IN FRONT OF V1. BY DRIVING ALONG SIDE THE VEHICLE, D1'S VIEW WAS OBSTRUCTED. V1 PULLED OUT AS V2 WAS PASSING BY. V1 COLLIDED WITH C1 CAUSING INJURY AND DAMAGE TO V2. V1 INITIALLY STOPPED BUT THEN DROVE OFF FROM THE SCENE.							Veh1, car, SE -> SW Veh2, pedal cycle, NE -> SW			Casualties 1 Vehicles 2	
31	Road No A258 Grid 636877E Section 109 Ref 152148N	SLIGHT	18/10/2018	5	09:40	L	Dry	Fine		R.TURN	GV
A258 LONDON RD J/W BOWLING GREEN LANE, DEAL (ORIGINAL COORDS - 636717,152022)									Dover		
V2 TURNED LEFT OUT OF THE HOSPITAL ONTO LONDON RD. V2 THEN INDICATED TO TURN LEFT ONTO BOWLING GREEN LANE. BEFORE V2 TURNED OFF THEIR INDICATOR, INTENDING TO CONTINUE ON LONDON RD INSTEAD OF TURNING ONTO BOWLING GREEN LANE, V1 PULLED OUT ONTO LONDON RD AND THE TWO VEHICLES COLLIDED. (AGE AND POSTCODE FOR V1 AND C2 NOT KNOWN)							Veh1, car, SW -> NE Veh2, goods < 3.5t, NW -> SW			Casualties 2 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
32	Road No A258 Grid 635581E Section 129 Ref 152476N	SERIOUS	28/12/2018	6	16:37	DRK STL	Wet/Damp	Other			
A258, LONDON RD J/W SHOLDEN NEW RD, SHOLDEN.									Dover		
V1 WAS TRAVELLING ON SANDWICH RD TOWARDS SANDWICH. V2 PARKED. V3 TRAVELLING SANDWICH RD TOWARDS DEAL. V1 ATTEMPTED TO OVERTAKE V2 AND COLLIDES WITH ITS REAR OFFSIDE AND THEN ROLLS. V3 COLLIDES WITH V1 AND IT HAS THEN COME TO REST IN THE MAIN CARRIAGEWAY.							Veh1, car, SE -> NW Veh2, car, P -> P Veh3, car, NW -> SE			Casualties 1 Vehicles 3	
33	Road No B2056 Grid 636846E Section Ref 151702N	SLIGHT	14/05/2019	3	14:53	L	Dry	Fine			
B2056 HAMILTON RD J/W MILL RD, DEAL									Dover		
V1 WAS TRAVELLING SOUTHWEST ON MILL RD AND FAILED TO STOP AT THE GIVE WAY JUNCTION WITH HAMILTON RD JUST AS V2 WAS PASSING IN FRONT OF V1, TURNING RIGHT ON THE BEND. THE TWO VEHICLES COLLIDED AND D1 GOT OUT TO SPEAK TO D2 BUT LEFT THE SCENE AS THEY WERE THREATENED BY D2'S ATTITUDE.							Veh1, car, NE -> SW Veh2, car, SW -> SE			Casualties 1 Vehicles 2	
34	Road No B2056 Grid 636526E Section 005 Ref 151670N	SLIGHT	13/07/2019	7	15:15	L	Dry	Fine			P/C
B2056 MANOR RD J/W ST LEONARDS RD, DEAL									Dover		
R1 was travelling northwest on Manor Rd when they saw another vehicle travelling towards them from an adjoining road. R1 swerved to move out of their way, failing to see V2 in front of them, which was parked at the side of the road.							Veh1, pedal cycle, SE -> NW Veh2, car, P -> P			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

D-PRINT CRASH REPORT

28-Oct-2020

08:00:57

Sholden, Deal

Accident Date BETWEEN '01-Jan-2015' AND '31-Dec-2019'

No	Location	Severity	Date	Day	Time	Street Lighting	Road Surface	Weather	Pedestrian Direction	Factors	Involved
35	Road No A258 Grid 635794E Section 125 Ref 152227N	SLIGHT	16/08/2019	6	11:45	L	Dry	Fine			
	A258 LONDON ROAD AT JW HALL CRESCENT, SHOLDEN DOVER									Dover	
Vehicle 1 was being pursued by Vehicle 2, a marked police vehicle. Vehicle 3 was travelling in the opposite direction towards Deal when Vehicle 1 has gone onto the wrong side of the road and made contact with Vehicle 3. Vehicle 1 has then left the scene							Veh1, car, SE -> NW Veh2, car, SE -> NW Veh3, taxi, NW -> SE			Casualties 1 Vehicles 3	
36	Road No A258 Grid 635591E Section 129 Ref 152466N	SERIOUS	15/09/2019	1	18:50	L	Dry	Fine		O/TAKE	M/C
	A258 LONDON RD J/W SHOLDEN NEW RD, SHOLDEN									Dover	
R1 WAS OVERTAKING V2 AND REMOVED THEIR FOOT OFF THE FOOTREST TO KICK THE MIRROR OF V2. THIS CAUSED R1 TO LOSE CONTROL AND HIT A TRAFFIC ISLAND BEFORE COMING OFF V1.							Veh1, m/cycle 125 - 500cc, SE -> NW Veh2, car, SE -> NW			Casualties 1 Vehicles 2	
37	Road No U Grid 637188E Section 001 Ref 152139N	SLIGHT	17/09/2019	3	19:50	DRK STL	Dry	Fine		R.TURN	M/C
	PARK AVE J/W MILL RD, SHOLDEN									Dover	
V1 STOPPED ON PARK AVE AT THE JUNCTION WITH MILL RD. R2 NOTICED THIS AND TRIED TO COME TO A STOP BUT COLLIDED WITH V1'S NEARSIDE BEFORE COMING OFF V2 AND GOING OVER V1'S BONNET, HITTING THE WINDSCREEN. V1 DROVE OFF FROM THE SCENE.							Veh1, car, N -> W Veh2, m/cycle 50 - 125cc, E -> W			Casualties 1 Vehicles 2	

Key Involved

PED Pedestrian
HGV Heavy Goods Vehicle
GV Goods Vehicle
M/C Motor Cycle
P/C Pedal Cycle
PSV Bus/Coach

Street Lighting

L Daylight

STL Street Lights
USL Street Lights Unlit
NSL No Street Lights
STU Street Lights Unknown

FACTORS

+VE Positive Breath Test
R.TURN Right Turn Manoeuvre
O/TAKE Overtaking Manoeuvre
S.VEH Single Vehicle

Special Conditions

ATS OUT Traffic Lights Not Working
ATS DEF Traffic Lights Defective
SIGNS Road Signs Defective or Obscured
RD WRKS Road Works
Surface Road Surface Defective

T18516
Sandwich Road, Sholden



Appendix D

Indicative Masterplan

Do not scale from this drawing.
 This drawing is for planning purposes only. It is not intended to be used for construction purposes. The accuracy of this drawing may be reliant upon survey information provided by third parties. Whilst all reasonable efforts are used to ensure drawings are accurate, edge Placemaking Group Ltd accept no responsibility or liability for any reliance placed on, or use of, this plan by anyone for purposes other than those stated above or for errors arising from third party information.

This drawing and the works depicted are the copyright of edge Placemaking Group Ltd.

PLANNING

- Site Boundary (4.99ha)
- Land in same ownership



Rev.	Date	Description
		Land South West of Sandwich Road, SHOLDEN

Illustrative Masterplan

Job ref: 275	Drawing number: P01	Revision: -
Scale: 1:1,500 @ A3	Date: March 2021	



part of
edge Placemaking Group Ltd
 Company Reg No 11447550 VAT No: 299072069

Suite 2
 7 Buttermarket
 Thame
 Oxfordshire
 OX9 3EW

 01865 522395
 enquiries@edgeUD.co.uk
 www.edgeUD.co.uk